


A large, light gray watermark of the Singer logo is centered on the page. It features a semi-circular arc at the top and bottom, with the word "SINGER" in a bold, sans-serif font in the middle. Below "SINGER" is the model number "145A304,404" in a smaller, sans-serif font. At the bottom of the arc is the word "CSMP" in a large, stylized, sans-serif font.

SINGER
145A304,404

CSMP



Ersatzteilleiste Pièces de rechange
Spare Parts Piezas de repuesto

SINGER

Teil-Nr	Benennung	Teil-Nr	Benennung	Teil-Nr	Benennung	Teil-Nr	Benennung	Teil-Nr	Benennung
G 005 068 3	Steilring L9	G 220 166 0	Gelenk J2	G 220 347 0	Kurbel, vorn F4	G 220 14 235 0	Schieber, links NA = 28 mm, o. Abb.	G 220 22 232 3	Obertransportfuß NA = 25 mm, o. Abb.
G 005 196 0	Druckröler J5, H5	G 220 167 0	Gelenkschraube J3	G 220 348 0	Nadeltransporthebe. F8	G 220 14 236 0	Schieber, rechts NA = 38 mm, o. Abb.	G 220 22 233 0	Stoffdruckerfuß NA = 25 mm, o. Abb.
G 005 220 0	Feder B3	G 220 168 0	Buchse, oben J2	G 220 350 0	Kurbel kpl. M9	G 220 14 237 0	Schieber, links NA = 38 mm, o. Abb.	G 220 22 236 3	Obertransportfuß NA = 30 mm, o. Abb.
G 008 357 0	Feder H5	G 220 169 0	Buchse, unten L3	G 220 351 0	Lagerzapfen L9	G 220 14 238 0	Schieber, rechts NA = 6 mm, o. Abb.	G 220 22 237 0	Stoffdruckerfuß NA = 30 mm, o. Abb.
G 016 401 0	Filzscheibe B3	G 220 170 0	Lufterhebelhalter J3	G 220 352 0	Zugstange K8	G 220 14 239 0	Schieber, links NA = 6 mm, o. Abb.	G 220 22 238 3	Obertransportfuß NA = 28 mm, o. Abb.
G 020 229 0	Unterlegscheibe C6	G 220 171 0	Boizen J2	G 220 373 0	Hubexzenter L1	G 220 15 007 0	Buchse, vorn K1	G 220 22 239 0	Stoffdruckerfuß NA = 28 mm, o. Abb.
G 030 031 0	Scheibe B3, G10	G 220 172 0	Stellring M2, M11	G 220 374 0	Gleitring L1	G 220 15 008 0	Buchse, mitte L4	G 220 22 240 3	Obertransportfuß NA = 38 mm, o. Abb.
G 030 218 0	Federscheibe D8	G 220 173 0	Sperrad K9	G 220 375 0	Gabel L2	G 220 15 009 0	Buchse, hinten K9	G 220 22 241 0	Stoffdruckerfuß NA = 38 mm, o. Abb.
G 037 100 0	Olrohr F4, F7	G 220 174 0	Spulengeh. kpl. H1	G 220 400 0	Kupplungswelle H6	G 220 15 012 0	Greiferröhre L6	G 220 22 242 3	Obertransportfuß NA = 5 mm, o. Abb.
G 037 129 0	Feder G10	G 220 175 0	Spule G3, K12	G 220 401 0	Kupplungsw. kpl. J6	G 220 15 013 0	Scheibe L9	G 220 22 243 0	Stoffdruckerfuß NA = 6 mm, o. Abb.
G 049 027 0	Federscheibe F8	G 220 180 0	Greifer kpl. J1	G 220 402 0	Seitenhandrad H9	G 220 16 004 0	Balken L3	G 220 23 201 4	Nadeistange NA = 4,8 mm, o. Abb.
G 053 220 0	Sicherung G9	G 220 181 4	Klappe G3	G 220 403 0	Seitenhandrad kpl. H9	G 220 16 005 0	Balken L3	G 220 23 202 4	Nadeistange NA = 3 mm, o. Abb.
G 061 106 0	Rosette B3	G 220 182 0	Druckfeder G3	G 220 404 0	Flansch H9	G 220 16 006 0	Stichplatte NA = 4,8 mm	G 220 23 203 4	Nadeistange NA = 10 mm, o. Abb.
G 067 018 0	Gleitthülse D3	G 220 183 0	Druckstift G3	G 220 405 0	Kupplungsscheibe J9	G 220 16 007 0	Stichplatte NA = 8 mm	G 220 23 204 4	Nadeistange NA = 12 mm, o. Abb.
G 067 241 0	Klammer L2	G 220 184 0	Spannstift G3	G 220 406 0	Buchse H6	G 220 16 008 0	Stichplatte NA = 10 mm	G 220 23 205 4	Nadeistange NA = 14 mm, o. Abb.
G 068 017 0	Boizen C2	G 220 185 0	Rad K2	G 220 407 0	Druckfeder H6	G 220 16 009 0	Stichplatte NA = 12 mm	G 220 23 206 4	Nadeistange NA = 15 mm, o. Abb.
G 068 041 0	Oldocht D2, F3, J2, D4	G 220 186 0	Deckring, rechts H3	G 220 408 0	Kupplung H6	G 220 16 010 0	Stichplatte NA = 14 mm	G 220 23 207 4	Nadeistange NA = 15 mm, o. Abb.
G 068 051 0	Kegelkerbstift F2	G 220 187 0	Deckring, links H3	G 220 409 0	Zahnrad E4	G 220 16 011 0	Stichplatte NA = 16 mm	G 220 23 208 4	Nadeistange NA = 15 mm, o. Abb.
G 068 157 0	Unterlegscheibe K3	G 220 188 0	Schutzwinkel H3	G 220 410 0	Zahnrad H6	G 220 16 012 0	Stichplatte NA = 18 mm	G 220 23 209 4	Nadeistange NA = 20 mm, o. Abb.
G 068 285 0	Olrohr G9	G 220 189 0	Greifer H1	G 220 411 3	Deckel F6	G 220 16 013 0	Stichplatte NA = 20 mm	G 220 23 210 4	Nadeistange NA = 20 mm, o. Abb.
G 068 533 0	Scheibe H6	G 220 190 0	Lenklaufbuchse K12	G 220 412 0	Riemenschutz A10	G 220 16 014 0	Stichplatte NA = 21 mm	G 220 23 211 4	Nadeistange NA = 20 mm, o. Abb.
G 081 156 0	Schraubenschlüssel A10	G 220 191 0	Sperrklinke L10	G 220 420 0	Oberteilstütze D8	G 220 16 015 0	Stichplatte NA = 22 mm	G 220 23 212 4	Nadeistange NA = 20 mm, o. Abb.
G 081 158 0	Pinzette L12	G 220 192 0	Boizen K10	G 220 421 0	Ölflangerblech L5	G 220 16 016 0	Stichplatte NA = 24 mm	G 220 23 213 4	Nadeistange NA = 20 mm, o. Abb.
G 088 232 0	Hülse H6	G 220 193 4	Hebel K11	G 220 442 0	Scharnier J4	G 220 16 017 0	Stichplatte NA = 25 mm	G 220 23 214 4	Nadeistange NA = 20 mm, o. Abb.
G 095 011 0	Olfriz L2	G 220 194 0	Gelenk L13	G 077 11 020 3	Garnrollenarm F12	G 220 16 018 0	Stichplatte NA = 26 mm	G 220 23 215 4	Nadeistange NA = 20 mm, o. Abb.
G 095 239 0	Haken C7, B7	G 220 195 0	Ruckschaltklinke K10	G 077 11 021 0	Teiler G11	G 220 16 019 0	Stichplatte NA = 28 mm	G 220 23 216 4	Nadeistange NA = 20 mm, o. Abb.
G 095 335 0	Schraube C2	G 220 196 0	Ruckschaltfeder K10	G 077 11 022 0	Auflage F11	G 220 16 020 0	Stichplatte NA = 30 mm	G 220 23 217 4	Nadeistange NA = 20 mm, o. Abb.
G 097 264 0	Rad J10	G 220 197 0	Rad L3, K2	G 077 11 023 0	Zentrierstück F11	G 220 16 021 0	Stichplatte NA = 32 mm	G 220 23 218 4	Nadeistange NA = 20 mm, o. Abb.
G 097 266 0	Feder H12	G 220 198 0	Zahnformriemen-Rad kpl. F10	G 077 11 024 3	Fadenleiter-Arm D12	G 220 16 022 0	Stichplatte NA = 34 mm	G 220 23 219 4	Nadeistange NA = 20 mm, o. Abb.
G 097 281 3	Platte K11	G 220 199 0	Zahnformriemen-Rad kpl. J10	G 077 11 025 0	Fadenleiter-Arm D12	G 220 16 023 0	Stichplatte NA = 36 mm	G 220 23 220 4	Nadeistange NA = 20 mm, o. Abb.
G 097 283 0	Boizen G10	G 220 200 0	Zahnformriemen-Rad kpl. F10	G 077 11 026 0	Rohr F12	G 220 16 024 0	Stichplatte NA = 38 mm	G 220 23 221 4	Nadeistange NA = 20 mm, o. Abb.
G 097 284 0	Ose G10	G 220 201 0	Scheibe L2	G 077 11 027 0	Ose F12	G 220 16 025 0	Transport, NA = 4,8 mm	G 220 23 222 4	Nadeistange NA = 20 mm, o. Abb.
G 097 285 0	Arm H11	G 220 202 0	Balken kpl. L3	G 100 03 015 0	Gewinde-Einsatz D9	G 220 16 026 0	Transport, NA = 8 mm	G 220 23 223 4	Nadeistange NA = 20 mm, o. Abb.
G 097 286 0	Boizen J12	G 220 203 0	Boizen L2	G 220 10 303 4	Oberteil kpl. F5, G9	G 220 16 027 0	Transport, NA = 10 mm	G 220 23 224 4	Nadeistange NA = 20 mm, o. Abb.
G 097 287 0	Boizen K12	G 220 204 0	Kurbel M2	G 220 10 004 0	Kopfdeckel G6	G 220 16 028 0	Transport, NA = 12 mm	G 220 23 225 4	Nadeistange NA = 20 mm, o. Abb.
G 097 288 0	Bremstück J10	G 220 205 0	Vorschubwelle L6	G 220 10 005 0	Deckel F8	G 220 16 029 0	Transport, NA = 14 mm	G 220 23 226 4	Nadeistange NA = 20 mm, o. Abb.
G 097 289 0	Klemme J10	G 220 206 0	Arreterbuchse G9	G 220 10 006 0	Deckel F7	G 220 16 030 0	Transport, NA = 15 mm	G 220 23 227 4	Nadeistange NA = 20 mm, o. Abb.
G 196 033 0	Fadenführungsstift F5	G 220 207 0	Boizen H9	G 220 10 007 0	Ölkasten F5	G 220 16 031 0	Transport, NA = 16 mm	G 220 23 228 4	Nadeistange NA = 20 mm, o. Abb.
G 220 003 0	Arm-Hinterteil G9	G 220 208 0	Roifenboizen F7	G 220 10 008 0	Ölkasten kpl. F5	G 220 16 032 0	Transport, NA = 18 mm	G 220 23 229 4	Nadeistange NA = 20 mm, o. Abb.
G 220 005 0	Lager, hinten E10	G 220 209 0	Unterlegscheibe F7	G 220 10 009 0	Aus-Össtift B3	G 220 16 033 0	Transport, NA = 20 mm	G 220 23 230 4	Nadeistange NA = 20 mm, o. Abb.
G 220 007 0	Lager, vorn E4	G 220 210 0	Zugstange G9	G 220 10 010 0	Stoffdruckerstange F1	G 220 16 034 0	Transport, NA = 22 mm	G 220 23 231 4	Nadeistange NA = 20 mm, o. Abb.
G 220 010 0	Arm-Mitteilteil H6	G 220 211 0	Weile L9	G 220 10 011 0	Buchse G1	G 220 16 035 0	Transport, NA = 24 mm	G 220 23 232 4	Nadeistange NA = 20 mm, o. Abb.
G 220 012 0	Lager, mitte-vorn D5	G 220 212 0	Umschaltkulisie M10	G 220 10 012 0	Scharnierplatte K12	G 220 16 036 0	Transport, NA = 26 mm	G 220 23 233 4	Nadeistange NA = 20 mm, o. Abb.
G 220 013 0	Lager D6	G 220 213 0	Umschaltkuli, kpl. M10	G 220 10 013 0	Schieber, links NA = 24 mm, o. Abb.	G 220 16 037 0	Transport, NA = 28 mm	G 220 23 234 4	Nadeistange NA = 20 mm, o. Abb.
G 220 016 0	Fadenhebel D2	G 220 214 0	Lagerzapfen L9	G 220 14 200 0	Schieber, rechts NA = 4,8 mm, o. Abb.	G 220 16 038 0	Transport, NA = 30 mm	G 220 23 235 4	Nadeistange NA = 20 mm, o. Abb.
G 220 016 4	Fadenhebel, kpl. D2	G 220 215 0	Zugfeder L11	G 220 14 201 0	Schieber, links NA = 4,8 mm, o. Abb.	G 220 16 039 0	Transport, NA = 32 mm	G 220 23 236 4	Nadeistange NA = 20 mm, o. Abb.
G 220 017 0	Handrad E10, C2	G 220 216 0	Nippel G11	G 220 14 202 0	Schieber, rechts NA = 4,8 mm, o. Abb.	G 220 16 040 0	Transport, NA = 34 mm	G 220 23 237 4	Nadeistange NA = 20 mm, o. Abb.
G 220 018 0	Lager D6	G 220 217 0	Umschaltgelenk M10	G 220 14 203 0	Schieber, links NA = 4,8 mm, o. Abb.	G 220 16 041 0	Transport, NA = 36 mm	G 220 23 238 4	Nadeistange NA = 20 mm, o. Abb.
G 220 019 0	Fad.-Führungswinkel H4	G 220 218 0	Umschaltgelenk, kpl. M10	G 220 14 204 0	Schieber, rechts NA = 4,8 mm, o. Abb.	G 220 16 042 0	Transport, NA = 38 mm	G 220 23 239 4	Nadeistange NA = 20 mm, o. Abb.
G 220 020 0	Führungsstift H4	G 220 219 0	Boizen M10	G 220 14 205 0	Schieber, links NA = 4,8 mm, o. Abb.	G 220 16 043 0	Transport, NA = 40 mm	G 220 23 240 4	Nadeistange NA = 20 mm, o. Abb.
G 220 021 0	Schutzbügel A3	G 220 220 0	Hebel L11	G 220 14 206 0	Schieber, rechts NA = 4,8 mm, o. Abb.	G 220 16 044 0	Transport, NA = 42 mm	G 220 23 241 4	Nadeistange NA = 20 mm, o. Abb.
G 220 022 3	Platte B1	G 220 221 0	Kulissenstein L10	G 220 14 207 0	Schieber, links NA = 4,8 mm, o. Abb.	G 220 16 045 0	Transport, NA = 44 mm	G 220 23 242 4	Nadeistange NA = 20 mm, o. Abb.
G 220 022 4	Platte kpl. B1	G 220 222 0	Lagerzapfen L10	G 220 14 208 0	Schieber, rechts NA = 4,8 mm, o. Abb.	G 220 16 046 0	Transport, NA = 46 mm	G 220 23 243 4	Nadeistange NA = 20 mm, o. Abb.
G 220 024 0	Auslösstift A1	G 220 223 0	Buchse M9	G 220 14 209 0	Schieber, links NA = 4,8 mm, o. Abb.	G 220 16 047 0	Transport, NA = 48 mm	G 220 23 244 4	Nadeistange NA = 20 mm, o. Abb.
G 220 025 0	Fadenstift A1	G 220 224 0	Flansch D7	G 220 14 210 0	Schieber, rechts NA = 4,8 mm, o. Abb.	G 220 16 048 0	Transport, NA = 50 mm	G 220 23 245 4	Nadeistange NA = 20 mm, o. Abb.
G 220 026 0	Fadenführung B1	G 220 225 0	Exzenter kpl. D7	G 220 14 211 0	Schieber, links NA = 4,8 mm, o. Abb.	G 220 16 049 0	Transport, NA = 52 mm	G 220 23 246 4	Nadeistange NA = 20 mm, o. Abb.
G 220 027 0	Winkel B1	G 220 226 0	Druckfeder M10	G 220 14 212 0	Schieber, rechts NA = 4,8 mm, o. Abb.	G 220 16 050 0	Transport, NA = 54 mm	G 220 23 247 4	Nadeistange NA = 20 mm, o. Abb.
G 220 029 0	Stellbuchse C2	G 220 227 0	Mutter L11	G 220 14 213 0	Schieber, links NA = 4,8 mm, o. Abb.	G 220 16 051 0	Transport, NA = 56 mm	G 220 23 248 4	Nadeistange NA = 20 mm, o. Abb.
G 220 030 0	Boizen C3	G 220 228 0	Kraftspul. kpl. J10	G 220 14 214 0	Schieber, rechts NA = 4,8 mm, o. Abb.	G 220 16 052 0	Transport, NA = 58 mm	G 220 23 249 4	Nadeistange NA = 20 mm, o. Abb.
G 220 031 0	Auslösestift A1	G 220 229 0	Ausdruckhebel J12	G 220 14 215 0	Schieber, links NA = 4,8 mm, o. Abb.	G 220 16 053 0	Transport, NA = 60 mm	G 220 23 250 4	Nadeistange NA = 20 mm, o. Abb.
G 220 032 0	Auslösebolzen B1	G 220 230 0	Weile H11	G 220 14 216 0	Schieber, rechts NA = 4,8 mm, o. Abb.	G 220 16 054 0	Transport, NA = 62 mm	G 220 23 251 4	Nadeistange NA = 20 mm, o. Abb.
G 220 033 0	Fadenrolle C3	G 220 231 0	Stift F5	G 220 14 217 0	Schieber, links NA = 4,8 mm, o. Abb.	G 220 16 055 0	Transport, NA = 64 mm	G 220 23 252 4	Nadeistange NA = 20 mm, o. Abb.
G 220 034 0	Fadenanz.-Feder B1	G 220 232 0	Druckfeder E6	G 220 14 218 0	Schieber, rechts NA = 4,8 mm, o. Abb.	G 220 16 056 0	Transport, NA = 66 mm	G 220 23 253 4	Nadeistange NA = 20 mm, o. Abb.
G 220 035 0	Auflage B1	G 220 233 0	Korbmutter E5	G 220 14 219 0	Schieber, links NA = 4,8 mm, o. Abb.	G 220 16 057 0	Transport, NA = 68 mm	G 220 23 254 4	Nadeistange NA = 20 mm, o. Abb.
G 220 036 0	Bügel C2	G 220 234 0	Fußhalter E5	G 220 14 220 0	Schieber, rechts NA = 4,8 mm, o. Abb.	G 220 16 058 0	Transport, NA = 70 mm	G 220 23 255 4	Nadeistange NA = 20 mm, o. Abb.
G 220 042 0	Kloben E3	G 220 235 0	Filzhalter E5	G 220 14 221 0	Schieber, links NA = 4,8 mm, o. Abb.	G 220 16 059 0	Transport, NA = 72 mm	G 220 23 256 4	Nadeistange NA = 20 mm, o. Abb.
G 220 043 0	Gelenk E3	G 220 236 0	Feder F5	G 220 14 222 0	Schieber, rechts NA = 4,8 mm, o. Abb.	G 220 16 060 0	Transport, NA = 74 mm	G 220 23 257 4	Nadeistange NA = 20 mm, o. Abb.
G 220 044 0	Boizen D3	G 220 237 0	Olfriz D10, D5, E5	G 220 14 223 0	Schieber, links NA = 4,8 mm, o. Abb.	G 220 16 061 0	Transport, NA = 76 mm	G 220 23 258 4	Nadeistange NA = 20 mm, o. Abb.
G 220 045 0	Kurbel F4	G 220 238 0	Olrohr H9	G 220 14 224 0	Schieber, rechts NA = 4,8 mm, o. Abb.	G 220 16 062 0	Transport, NA = 78 mm	G 220 23 259 4	Nadeistange NA = 20 mm, o. Abb.
G 220 047 0	Boizen D2	G 220 239 0	Feder B9	G 220 14 225 0	Schieber, links NA = 4,8 mm, o. Abb.	G 220 16 063 0	Transport, NA = 80 mm	G 220 23 260 4	Nadeistange NA = 20 mm, o. Abb.
G 220 056 0	Blattfeder C5	G 220 240 0	Lufterhebel B4	G 220 14 226 0	Schieber, rechts NA = 4,8 mm, o. Abb.	G 220 16 064 0	Transport, NA = 82 mm	G 220 23 261 4	Nadeistange NA = 20 mm, o. Abb.
G 220 057 0	Verstärkung C5	G 220 241 0	Lufterhebel B4	G 220 14 227 0	Schieber, links NA = 4,8 mm, o. Abb.	G 220 16 065 0	Transport, NA = 84 mm	G 220 23 262 4	Nadeistange NA = 20 mm, o. Abb.
G 220 058 3	Regulierschraube B5	G 220 242 0	Stellring B7	G 220 14 228 0	Schieber, rechts NA = 4,8 mm, o. Abb.	G 220 16 066 0	Transport, NA = 86 mm	G 220 23 263 4	Nadeistange NA = 20 mm, o. Abb.
G 220 062 0	Buchse C1	G 220 243 0	Boizen B5	G 220 14 229 0	Schieber, links NA = 4,8 mm, o. Abb.	G 220 16 067 0	Transport, NA = 88 mm	G 220 23 264 4	Nadeistange NA = 20 mm, o. Abb.
G 220 063 0	Buchse, unten C1	G 220 244 0	Feder B6	G 220 14 230 0	Schieber, rechts NA = 4,8 mm, o. Abb.	G 220 16 068 0	Transport, NA = 90 mm	G 220 23 265 4	Nadeistange NA = 20 mm, o. Abb.
G 220 064 0	Kloben F1	G 220 245 0	Stift B5	G 220 14 231 0	Schieber, links NA = 4,8 mm, o. Abb.	G 220 16 069 0	Transport, NA = 92 mm	G 220 23 266 4	Nadeistange NA = 20 mm, o. Abb.
G 220 065 0	Boizen G1	G 220 246 0	Feststellgriff kpl. B7	G 220 14 232 0	Schieber, rechts NA = 4,8 mm, o. Abb.	G 220 16 070 0	Transport, NA = 94 mm	G 220 23 267 4	Nadeistange NA = 20 mm, o. Abb.
G 220 068 0	Federkloben F1	G 220 247 0	Exzenter D5	G 220 14 233 0	Schieber, links NA = 4,8 mm, o. Abb.	G 220			

145A 304; 404

Teil-Nr		Benennung	Teil-Nr	Benennung	Teil-Nr	Benennung	Teil-Nr	Benennung	Teil-Nr	Benennung
G 992 00 982 0		Stift	M10	Nähgarnituren	NA = 24 mm		NA = 8 mm		NA = 28 mm	
G 992 01 184 0		Schraube	L9	Klasse 145A-304	G 220 23 211 4		G 220 23 202 4		G 220 23 218 4	
G 992 01 289 0		Schraube	H4, C2		G 220 22 223 0		G 220 22 205 0		G 220 22 239 0	
G 992 01 344 0		Schraube	G6		G 220 22 223 3		G 220 22 204 3		G 220 22 238 3	
G 992 01 383 0		Mutter	J1	NA = 4,8 mm	7 x 23 Nr. 140-160		7 x 23 Nr. 170-200		7 x 23 Nr. 170-200	
G 992 01 386 0		Schraube	F1, C1	G 220 23 201 4	Nadelstange kpl.		G 220 20 211 0		G 220 20 219 0	
G 992 01 393 0		Mutter	E8	G 220 22 208 0	Stoffdruckerfuß		G 220 21 229 0		G 220 21 237 0	
G 992 01 395 0		Schraube	C2, B7	G 220 22 202 3	Obertransportfuß		G 220 14 101 0		G 220 14 235 0	
G 992 01 420 0		Schraube	L3	7 x 23 Nr. 140-160	Nadel		G 220 14 220 0		G 220 14 234 0	
G 992 01 451 0		Mutter	C1	G 220 20 201 0	Stichplatte		G 220 20 202 0		G 220 20 219 0	
G 992 01 495 0		Schraube	L11, M1	G 220 21 219 0	Transporteur		G 220 21 220 0		G 220 21 237 0	
G 992 01 520 0		Mutter	B2	G 220 14 201 0	Schieber, links		G 220 14 203 0		G 220 14 235 0	
G 992 01 536 0		Schraube	E5	G 220 14 200 0	Schieber, rechts		G 220 14 202 0		G 220 14 234 0	
G 992 01 577 0		Schraube	B5, M3		NA = 25 mm		NA = 10 mm		NA = 30 mm	
G 992 01 585 0		Schraube	E8	NA = 6 mm	G 220 23 212 0		G 220 23 203 4		G 220 23 217 4	
G 992 01 618 0		Paßstift	F6, F7	G 220 23 220 4	Nadelstange kpl.		G 220 22 207 0		G 220 22 237 0	
G 992 01 675 0		Schraube	H6	G 220 22 248 0	Stoffdruckerfuß		G 220 22 206 3		G 220 22 236 3	
G 992 01 677 0		Schraube	J6	G 220 22 242 3	Obertransportfuß		7 x 23 Nr. 170-200		7 x 23 Nr. 170-200	
G 992 01 684 0		Schraube	F7, F6	7 x 23 Nr. 140-160	Nadel		7 x 23 Nr. 170-200		7 x 23 Nr. 170-200	
G 992 01 703 0		Schraube	H3	G 220 20 221 0	Stichplatte		G 220 20 203 0		G 220 20 218 0	
G 992 01 747 0		Schraube	K3	G 220 21 229 0	Transporteur		G 220 21 221 0		G 220 21 236 0	
G 992 01 765 0		Schraube	K5	G 220 14 239 0	Schieber, links		G 220 14 205 0		G 220 14 233 0	
G 992 01 766 0		Schraube	K12, K2	G 220 14 238 0	Schieber, rechts		G 220 14 204 0		G 220 14 232 0	
G 992 01 767 0		Schraube	F3, H2		NA = 28 mm		NA = 12 mm		NA = 32 mm	
G 992 01 768 0		Schraube	H9	NA = 8 mm	G 220 23 218 4		G 220 23 204 4		G 220 23 216 4	
G 992 01 769 0		Schraube	H6, B3, B1	G 220 23 202 4	Nadelstange kpl.		G 220 22 209 0		G 220 22 232 3	
G 992 01 770 0		Schraube	G2, J2	G 220 22 205 0	Stoffdruckerfuß		G 220 22 208 3		G 220 22 230 0	
G 992 01 772 0		Schraube	D3	G 220 22 204 3	Obertransportfuß		7 x 23 Nr. 170-200		7 x 23 Nr. 170-200	
G 992 01 777 0		Schraube	H3	7 x 23 Nr. 140-160	Nadel		7 x 23 Nr. 170-200		7 x 23 Nr. 170-200	
G 992 01 778 0		Schraube	H3	G 220 20 202 0	Stichplatte		G 220 20 204 0		G 220 20 216 0	
G 992 01 779 0		Schraube	H4	G 220 21 220 0	Transporteur		G 220 21 222 0		G 220 21 231 0	
G 992 01 783 0		Schraube	L2	G 220 14 208 0	Schieber, links		G 220 14 207 0		G 220 14 231 0	
G 992 01 785 0		Schraube	L3	G 220 14 202 0	Schieber, rechts		G 220 14 206 0		G 220 14 230 0	
G 992 01 786 0		Mutter	F8		NA = 30 mm		NA = 14 mm		NA = 38 mm	
G 992 01 787 0		Mutter	M11, M9	NA = 10 mm	G 220 23 217 4		G 220 23 205 4		G 220 23 219 4	
G 992 01 788 0		Schraube	F2	G 220 23 208 4	Nadelstange kpl.		G 220 22 211 0		G 220 22 241 0	
G 992 01 789 0		Schraube	M10	G 220 22 207 0	Stoffdruckerfuß		G 220 22 210 0		G 220 22 240 3	
G 992 01 791 0		Schraube	E1	G 220 22 206 3	Obertransportfuß		7 x 23 Nr. 170-200		7 x 23 Nr. 170-200	
G 992 01 792 0		Schraube	K2	7 x 23 Nr. 140-160	Nadel		7 x 23 Nr. 170-200		7 x 23 Nr. 170-200	
G 992 01 794 0		Schraube	L5	G 220 20 208 0	Stichplatte		G 220 20 205 0		G 220 20 220 0	
G 992 01 795 0		Schraube	J4	G 220 21 221 0	Transporteur		G 220 21 223 0		G 220 21 238 0	
G 992 01 796 0		Schraube	L3	G 220 14 205 0	Schieber, links		G 220 14 209 0		G 220 14 237 0	
G 992 01 797 0		Schraube	K2	G 220 14 204 0	Schieber, rechts		G 220 14 208 0		G 220 14 236 0	
G 992 01 798 0		Schraube	K11		NA = 32 mm		NA = 15 mm		NA = 45 mm	
G 992 01 816 0		Schraube	C6	G 220 23 218 4	Nadelstange kpl.		G 220 23 206 4		G 220 23 213 4	
G 992 01 817 0		Schraube	F8	G 220 22 233 0	Stoffdruckerfuß		G 220 22 213 0		G 220 22 227 0	
G 992 01 818 0		Schraube	E9	G 220 22 232 3	Obertransportfuß		G 220 22 212 3		G 220 22 226 3	
G 992 01 819 0		Schraube	F2	7 x 23 Nr. 140-160	Nadel		7 x 23 Nr. 170-200		7 x 23 Nr. 170-200	
G 992 01 820 0		Schraube	B7	G 220 20 216 0	Stichplatte		7 x 23 Nr. 170-200		7 x 23 Nr. 170-200	
G 992 01 823 0		Schraube	A1	G 220 21 231 0	Transporteur		G 220 20 206 0		G 220 20 213 0	
G 992 01 830 0		Boizen	D1	G 220 14 231 0	Schieber, links		G 220 21 224 0		G 220 21 232 0	
G 992 01 832 0		Schraube	K2, K12	G 220 14 230 0	Schieber, rechts		G 220 14 211 0		G 220 14 225 0	
G 992 01 861 0		Schraube	D8	G 220 14 230 0	Schieber, rechts		G 220 14 210 0		G 220 14 224 0	
G 992 01 916 0		Schraube	E8, M9		NA = 38 mm		NA = 16 mm		NA = 50 mm	
G 992 01 917 0		Schraube	J2	NA = 14 mm	G 220 23 219 4		G 220 23 207 4		G 220 23 214 4	
G 992 02 000 0		Schraube	D9	G 220 23 205 4	Nadelstange kpl.		G 220 22 241 0		G 220 22 229 0	
G 992 02 020 0		Lasche	B8	G 220 22 211 0	Stoffdruckerfuß		G 220 22 240 3		G 220 22 228 3	
G 992 02 021 3		Riemenschutz kpl.	D9	G 220 22 210 0	Obertransportfuß		7 x 23 Nr. 140-160		7 x 23 Nr. 170-200	
G 992 02 023 0		Mutter	G2	G 220 22 212 3	Stichplatte		G 220 22 215 0		G 220 20 214 0	
G 992 02 420 0		Gewindeeinsatz	D4	7 x 23 Nr. 140-160	Nadel		G 220 22 214 3		G 220 21 233 0	
G 992 02 144 0		Schraube	D4	G 220 20 205 0	Stichplatte		G 220 21 225 0		G 220 14 227 0	
G 992 02 144 0		Schraube	D4	G 220 21 228 0	Transporteur		G 220 14 213 0		G 220 14 226 0	
G 992 02 144 0		Schraube	D4	G 220 14 208 0	Schieber, links		G 220 14 212 0		NA = 60 mm	
G 992 02 144 0		Schraube	D4	G 220 14 208 0	Schieber, rechts		NA = 18 mm		G 220 23 215 4	
G 992 03 152 3		Schraube	G12, D12	NA = 15 mm	G 220 22 227 0		G 220 23 208 4		G 220 22 231 0	
G 992 03 152 3		Schraube	K6	G 220 23 206 4	Nadelstange kpl.		G 220 22 217 0		G 220 22 230 3	
G 992 03 155 0		Schraube	J10	G 220 22 218 0	Stoffdruckerfuß		G 220 22 216 3		7 x 23 Nr. 170-200	
G 992 03 155 0		Schraube	D10	G 220 22 212 3	Obertransportfuß		G 220 20 213 0		G 220 20 215 0	
G 992 03 155 0		Schraube	K12	G 220 20 212 3	Stichplatte		G 220 21 232 0		G 220 21 234 0	
G 992 03 156 3		Schraube	H12	G 220 23 212 3	Transporteur		G 220 14 225 0		G 220 14 229 0	
G 992 03 158 3		Flüge schraube	C9	7 x 23 Nr. 140-160	Nadel		G 220 14 224 0		G 220 14 228 0	
G 992 03 144 0		Schraube	D4	G 220 20 206 0	Stichplatte		G 220 20 208 0		G 220 14 229 0	
G 992 03 337 8		Mutter	F12, C12	G 220 21 228 0	Transporteur		G 220 21 226 0		G 220 14 228 0	
G 992 07 029 0		Stift	F3	G 220 14 211 0	Schieber, links		G 220 14 215 0		NA = 20 mm	
G 992 08 078 0		Stift	D1	G 220 14 210 0	Schieber, rechts		G 220 23 209 4		G 220 23 210 4	
G 992 08 089 0		Stift	H6		NA = 16 mm		G 220 22 219 0		G 220 22 219 0	
G 992 08 146 3		Unterlegscheibe	J10	G 220 23 207 4	Nadelstange kpl.		G 220 22 218 3		G 220 22 218 3	
G 992 08 146 3		Unterlegscheibe	J10	G 220 22 215 0	Stoffdruckerfuß		7 x 23 Nr. 170-200		7 x 23 Nr. 170-200	
G 992 08 146 3		Unterlegscheibe	J10	G 220 22 214 3	Obertransportfuß		G 220 20 209 0		G 220 20 210 0	
G 992 08 146 3		Unterlegscheibe	J10	7 x 23 Nr. 140-160	Nadel		G 220 21 227 0		G 220 21 228 0	
G 992 08 146 3		Unterlegscheibe	J10	G 220 20 207 0	Stichplatte		G 220 14 217 0		G 220 14 218 0	
G 992 08 146 3		Unterlegscheibe	J10	G 220 21 225 0	Transporteur		G 220 14 216 0		NA = 24 mm	
G 992 08 146 3		Unterlegscheibe	J10	G 220 14 215 0	Schieber, links		G 220 23 210 4		G 220 23 211 4	
G 992 08 146 3		Unterlegscheibe	J10	G 220 14 212 0	Schieber, rechts		G 220 22 220 3		G 220 22 223 0	
G 992 08 146 3		Unterlegscheibe	J10	G 220 14 212 0	Schieber, rechts		7 x 23 Nr. 170-200		7 x 23 Nr. 170-200	
G 992 08 146 3		Unterlegscheibe	J10	G 220 14 212 0	Schieber, rechts		G 220 20 210 0		G 220 20 211 0	
G 992 08 146 3		Unterlegscheibe	J10	G 220 14 212 0	Schieber, rechts		G 220 21 228 0		G 220 21 229 0	
G 992 08 146 3		Unterlegscheibe	J10	G 220 14 212 0	Schieber, rechts		G 220 14 219 0		G 220 14 220 0	
G 992 08 146 3		Unterlegscheibe	J10	G 220 14 212 0	Schieber, rechts		G 220 14 218 0		NA = 25 mm	
G 992 08 146 3		Unterlegscheibe	J10	G 220 14 212 0	Schieber, rechts		G 220 23 212 0		G 220 23 213 0	
G 992 08 146 3		Unterlegscheibe	J10	G 220 14 212 0	Schieber, rechts		G 220 22 233 0		G 220 22 233 0	
G 992 08 146 3		Unterlegscheibe	J10	G 220 14 212 0	Schieber, rechts		G 220 22 232 3		G 220 22 232 3	
G 992 08 146 3		Unterlegscheibe	J10	G 220 14 212 0	Schieber, rechts		7 x 23 Nr. 170-200		7 x 23 Nr. 170-200	
G 992 08 146 3		Unterlegscheibe	J10	G 220 14 212 0	Schieber, rechts		G 220 20 210 0		G 220 20 211 0	
G 992 08 146 3		Unterlegscheibe	J10	G 220 14 212 0	Schieber, rechts		G 220 21 231 0		G 220 21 231 0	
G 992 08 146 3		Unterlegscheibe	J10	G 220 14 212 0	Schieber, rechts		G 220 14 230 0		G 220 14 230 0	
G 992 08 146 3		Unterlegscheibe	J10	G 220 14 212 0	Schieber, rechts		G 220 14 230 0		G 220 14 230 0	
G 992 08 146 3		Unterlegscheibe	J10	G 220 14 212 0	Schieber, rechts		G 220 14 230 0		G 220 14 230 0	
G 992 08 146 3		Unterlegscheibe	J10	G 220 14 212 0	Schieber, rechts		G 220 14 230 0		G 220 14 230 0	
G 992 08 146 3		Unterlegscheibe	J10	G 220 14 212 0	Schieber, rechts		G 220 14 230 0		G 220 14 230 0	
G 992 08 146 3		Unterlegscheibe	J10	G 220 14 212 0	Schieber, rechts		G 220 14 230 0		G 220 14 230 0	
G 992 08 146 3		Unterlegscheibe	J10	G 220 14 212 0	Schieber, rechts		G 220 14 230 0		G 220 14 230 0	
G 992 08 146 3		Unterlegscheibe	J10	G 220 14 212 0	Schieber, rechts		G 220 14 230 0		G 220 14 230 0	
G 992 08 146 3		Unterlegscheibe	J10	G 220 14 212 0	Schieber, rechts		G 220 14 230 0		G 220 14 230 0	
G 992 08 146 3		Unterlegscheibe	J10	G 220 14 212 0	Schieber, rechts		G 220 14 230 0		G 220 14 230 0	
G 992 08 146 3		Unterlegscheibe	J10	G 220 14 212 0	Schieber, rechts		G 220 14 230 0		G 220 14 230 0	
G 992 08 146 3		Unterlegscheibe	J10	G 220 14 212 0	Schieber, rechts		G 220 14 230 0		G 220 14 230 0	
G 992 08 146 3		Unterlegscheibe	J10	G 220 14 212 0	Schieber, rechts		G 220 14 230 0		G 220 14 230 0	
G 992 08 1										